

PULL OUT TORQUE CURVE OF 17HS13-1334S

1.33A/PHASE HALF STEP —●— 24V

